


A (x1)




B (x1)




C (x2)

2



1



*Note: Adjust the spacer A1, allowing the mounting hole on it to be aligned to the screw.*

